

## 2012 TOYOTA PRIUS 1.8L L4

JTDKN3DU8C1547749

### 1 Confirmed Code

**U0101** Lost Communication with TCM

### 1 Pending Code

**U0101** Lost Communication with TCM

### 1 Permanent Code

**U0101** Lost Communication with TCM

### 3 Instrument Panel Control Module / PATS Codes

**U0104-** Lost Communication With Cruise Control Module: No Sub Type Information

**00**

CONFIRMED

**U3003-** Battery Voltage: Circuit Voltage Below Threshold

**16**

CONFIRMED

**U0101-** Lost Communication with TCM: No Sub Type Information

**00**

CONFIRMED

### 1 Generic / Body Electronic Module (TPMS / PATS) Code

**U0101-** Lost Communication with TCM: No Sub Type Information

**00**

CONFIRMED

### 1 Powertrain Control Module Code

**U0104-** Lost Communication With Cruise Control Module: No Sub Type Information

**00**

CONFIRMED/P  
ENDING

### 1 Transmission Control Module Code

**U0073-** Control Module Communication Bus "A" Off: No Sub Type Information

**00**

CONFIRMED/P  
ENDING

### 1 Blind Spot Monitoring (Left) Code

**U0423-** Invalid Data Received From Instrument Panel Cluster Control Module: Event  
**68** Information

CONFIRMED

### 3 Forward Sensing Camera Codes

**U0104-** Lost Communication With Cruise Control Module: No Sub Type Information

**00**

CONFIRMED

**U0415-** Invalid Data Received From Anti-Lock Brake System (ABS) Control Module: Event  
**68** Information

CONFIRMED

**U0423-** Invalid Data Received From Instrument Panel Cluster Control Module: Event  
**68** Information

CONFIRMED

### 1 Remote Keyless Entry Code

**U0101-** Lost Communication with TCM: No Sub Type Information

**00**

CONFIRMED

**Disclaimer:** This information is provided without warranty and is subject to the Terms of Use posted at [www.bluedriver.com/eula.html](http://www.bluedriver.com/eula.html). Reproduction of this information or any portion thereof constitutes infringement of copyright.